

Spare Parts Catalogue

MD-CO-RO-22

MODELS TYPE : (5085DE0, 5085EVO
5085EV1, 5085ELO)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2.2	02	27	Washer	C00217	C01265	NY	Old code was wrong
2.1	02	26	Screw	C00920	C01518	YY	
2.1	03	21	Motherboard	AM2010-75?	AM10-085?	YY	Full compatibility with 2014 robot
2.1	04	01	Battery Charger	50_E0009_00	HLN60H29ZU	YY	
2.1	04	02	Complete base	075Z06200A	075Z06200A_V15	YY	New base with a new transmitter.
2.1	04	04	Transmitter	050Z22700A	051Z17100A	NY	Please check the technical training note, to understand how to fix it, how to fix the wire connection and which features are available.
2.1	04	06	Recharging supply cable	CB01_5075RIC_V0	CB01_85S2	NN	



Spare Parts Catalogue

MD-CO-RO-23

MODELS TYPE : (9L3BL , 9L3LL)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2.9	02	12	Screw	300_A0058_00	300Z20300A	YY	
2.9	04	10	Motherboard	AM2000-10-3L	AM2010-10-3L	YY	
2.9	04	25	Battery	CS_C0114	300Z20800A	NN	Exchange "YY" With CB02_ADTPS item
2.9	04	25	Wire adapter		CB02_ADTPS		New Item for new battery
2.8	02	20	Bell	300Z00100A	300Z18800B	YY	
2.8	04	36	Gasket		300_C0009_00	YY	New Item
2.7	01	07	Kit for charging	AMBR300RN	50_E0011_00	YY	Connection to the power supply instead of the transmitter.



Spare Parts Catalogue

MD-CO-RO-23
MODELS TYPE :
(5300E0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Code	New-Code	Exchang.	Note
5.2	02	18	Rubber	300Z21600B 110Z05000A			No longer available.
5.1	03	7	Molla - Spring	025_D0082	300Z23400A	NY	
5.1	04	16	Gasket	300_C0009_00	300C000901	NY	



Spare Parts Catalogue

MD-CO-RO-25

MODELS TYPE :

(5200BA0, 5200DE0, 5200EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	<i>Old and new components can be installed on new and old robots (interchangeability in both directions)</i>
NY	<i>The new components can be installed both on new and old robots whereas old components can not be installed on new robots.</i>
NN	<i>The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).</i>

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Code	New-Code	Exchang.	Note
5.1	03	44	Screw	C00603	C00041	NY	Old code was wrong



Spare Parts Catalogue

MD-CO-RO-32

MODELS TYPE :
(5030BA0 - 5030DE0 - 5030EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2.2	04	08	Cover		051Z03800B black	YY	New item added. Check the color.
2.1	01	01	Screwdriver	110Z23900A	051Z20600A	NY	Old code was wrong
2.1	02	22a	Blade		075Z07800A	YY	New item added.
2.1	03	32	Gasket		051Z20000A	NN	New item added.
2.1	03	33	Gasket		051Z20100A	NN	New item added.
2.1	03	34	Washer		C00070	NN	New item added.
2.1	03	35	Screw		C01333	NN	New item added.
2.1	03	36	Cup		C01583	NN	New item added.



Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2.0	02	14	Recharge Cabling	CB02_L30 (on 2014 Robot)	CB02_PCL30	NN	
2.0	03	10	Gasket	C01151 (on 2014 Robot)	C01390	YY	
2.0	03	26	Elastic plate	075Z08700A (on 2014 Robot)	051Z05400B	YY	
2.0	04	01	Battery Charger	50_E0009_00 (on 2014 Robot)	HLN60H29ZU	YY	
2.0	04	04	Transmitter	050Z22700A (on 2014 Robot)	051Z17100A	NY	Please check the technical training note, to understand how to fix it, how to fix the wire connection and which features are available.
2.0	04	06	Recharging supply cable	CB01_30RIC_V0 (2014 Robot)	CB01_30S2	NN	