

# Spare Parts Catalogue

MD-CO-RO-22

MODELS TYPE : (5085DE0, 5085EVO  
5085EV1, 5085ELO)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2016 Robots							
2.4	03	21	Mother Board	AM10-085xx	AM11-085xx	YY	Replace Code
2.4	04	01	(2A) Battery Charger	HLN60H29ZU	OWA60E30	YY	Replace item & Code
2.3	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.3	01	03	Nails	AMBCHFEFI	200A00200A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.3	01	09	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
2.3	02	10 11 12	Wheel fixing system	C01209 C00360 C00361	C01767 C00361 C01766	YY	New wheels fixing system
2.3	02	20	Bell	075Z07600A.1	075Z07600AB	YY	
2.3	04	02	Complete Base	075Z06200A_V15	075Z06200A_15N	YY	
2.3	04	07	Plate support	075Z06300A.1	075Z06300A.3	YY	
2.3	04	08	Clips	C01101	C01559	YY	
2015 Robots							
2.2	02	27	Washer	C00217	C01265	NY	Old code was wrong
2.1	02	26	Screw	C00920	C01518	YY	

2.1	03	21	Motherboard	AM2010-75?	AM10-085?	YY	Full compatibility with 2014 robot
2.1	04	01	Battery Charger	50_E0009_00	HLN60H29ZU	YY	
2.1	04	02	Complete base	075Z06200A	075Z06200A_V15	YY	New base with a new transmitter.
2.1	04	04	Transmitter	050Z22700A	051Z17100A	NY	Please check the technical training note, to understand how to fix it, how to fix the wire connection and which features are available.
2.1	04	06	Recharging supply cable	CB01_5075RIC_V0	CB01_85S2	NN	



# Spare Parts Catalogue

MD-CO-RO-23

MODELS TYPE :  
(5300EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components cannot be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TA B.	RI F.	Description	Old-Code	New-Code	Exc.	Note
2016 Robots							
5.5	04	30	Cabling CPU-Display	CB01_D16_V1	CB01_DI6	YY	Replace Code
5.5	04	36	Mother Board	AM10-300RL	AM11-300RL	YY	Replace Code
5.5	05		Reference 13 – Roof – on the previous spare part catalogue				No longer available
5.5	05	15	Arch		030Z13000A	NY	New item added
5.4	02	32	Screw	C00781	C01246	NY	New item added
5.4	02	39	Washer		C01759	YY	New item added
5.4	02	40	Washer		C01247	YY	New item added
5.4	03	22	Sege		C01936	YY	New item added.
5.4	03	11	Keyboard	300Z07900A	300Z18500A	YY	New code should be used on the cover with Stop button
5.4	04	39	Cabling		CB14_ADTPS	YY	New item added to manage old motherboard with new battery connector.
5.3	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	Docking base without countersunk holes : use old item code
5.3	01	03	Nails	AMBCHFEFI	200A00200A	YY	Docking base without countersunk holes : use old item code
5.3	01	10	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
5.3	02	3	Gasket	025_D0080	025_D0080.4	YY	Material & Price review
5.3	02	8	Cap set	300Z17500A.R	300Z17500ABR	YY	Material & Price review
5.3	03	5	Support	025_D0048_01	025_D0048_01B	YY	Material

5.3	03	20	Upper body	300_A0040_02	300_A0040_02	YY	Material & Price review
5.3	03	21	Under body	300Z21300C	300Z21300C	YY	Material & Price review
5.3	05	4	Charging base	030Z12500A_15	030Z12500AE	YY	Material & Price review
2015 Robots							
5.2	02	18	Rubber	300Z21600B 110Z05000A			No longer available.
5.1	03	7	Molla - Spring	025_D0082	300Z23400A	NY	
5.1	04	16	Gasket	300_C0009_00	300C000901	NY	



# Spare Parts Catalogue

MD-CO-RO-25

MODELS TYPE :

(5200BA0, 5200DE0, 5200EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2016 Robots							
5.2	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
5.2	01	03	Nails	AMBCHFEFI	200A00200A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
5.2	01	10	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
5.2	05	2	Charging base	Check code		YY	Material & Price review
2015 Robots							
5.1	03	44	Screw	C00603	C00041	NY	Old code was wrong



# Spare Parts Catalogue

**MD-CO-RO-27**

**MODELS TYPE :**

**(520RBA0, 520RDE0, 520RELO)**

*This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.*

*The reading of the degree of interchangeability of the new components is explained in the following table:*

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2016 Robots							
5.2	03	03	Wire		CB01_HR200E	YY	X white power connector on motherboard side  Use CB01_L200E.0 & CB02_L200E.0 on green connectors on motherboard side
5.2	05	11	Arch		030Z09800A	YY	New item added.
5.1	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
5.1	01	03	Nails	AMBCHFEFI	200A00200A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
5.1	01	10	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
5.1	02	3	Gasket	025_D0080	025_D0080.4	YY	Material & Price review
5.1	02	9	Support	110Z00700A	110Z00700AE	YY	Material
5.1	02	30	Protection		110Z25400A	YY	New item added.

5.1	05	2	Charging base	Same item code 030Z02300A_15 BA200R_BDE	YY	Material & Price review
-----	----	---	---------------	---	----	-------------------------



# Spare Parts Catalogue

MD-CO-RO-29

MODELS TYPE :  
(NT60)

*This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.*

*The reading of the degree of interchangeability of the new components is explained in the following table:*

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item		New-Item	Exchang.	Note
1.31	01		(KIT) New Fin	7456		7573	YY	New item added.
1.31	01		Threaded sleeve			7567	YY	New item added. Use with new 7573
1.31	01		Spacer ring			7568	YY	New item added. Use with new 7573
1.31	01		O-Ring			7570	YY	New item added. Use with new 7573
1.31	01		Flaxible tube			7571	YY	New item added. Use with new 7573
1.31	01		New Fin	7456		7572	YY	New item added.





# Spare Parts Catalogue

**MD-CO-RO-31**

**MODELS TYPE :**

**( 5400BA0, 5400DE0, 5400EL0 )**

*This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.*

*The reading of the degree of interchangeability of the new components is explained in the following table:*

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2016 Robots							
2.2	03	40	Arm Cover		400D00019	YY	New item added.
2.2	03	41	Arm Body		400D00015	YY	New item added.
2.2	04	18	GPS Cabling		C01503	YY	New item added.
2.1	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.1	01	03	Nails	AMBCHFEFI	200A00200A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.1	01	10	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
2.1	02	3	Gasket	025_D0080	025_D0080.4	YY	Material & Price review
2.1	02	9	Support	110Z00700A	110Z00700AE	YY	Material
2.1	ALL	ALL					5400DE0 & 5400EL0 models



# Spare Parts Catalogue

MD-CO-RO-32

MODELS TYPE :  
(5030BA0 - 5030DE0 - 5030EL0 - 6030EP0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2016 Robots							
2.5	02	06	Mother Board	AM2010-30xx	AM2011-30xx	YY	Replace Code
2.5	02	40	Spring		C01185	YY	New item added
2.5	02	41	Screw		C00087	YY	New item added
2.5	03	40	Gasket		051Z29100A	YY	New item added.
2.5	04	01	(2A) Battery Charger	HLN60H29ZU	OWA60E30	YY	Replace item & Code
2.5	04	01	(5A) Battery Charger		CS_CLG150-30	YY	New item added. Use only on the new model with 3 batteries "6030EP0"
2.4	02	39	Wheel cup		CS_D0183_04	YY	New item added.
2.4	03	12	Screw	C00210	C00208	<b>NN</b>	<b>Use on 2016 Robot. Old robot needs C00210</b>
2.4	03	16	Cabling Motherboard to battery		CB03_HR30	<b>NN</b>	<b>Viewing in figure at TAB 3, use Ref. 16 : CB03_HR03 or Ref. 16a : CB03_L30</b>
2.4	03	25	Washer		C01925	YY	New item added.
2.4	03	37	Under body	051Z04300HA	051Z04300HA	YY	Move from TAB 2.RIF 29
2.4	03	38	Under body		051A21500A	YY	New item added.
2.4	03	39	Sege		C01936	YY	New item added.

2.3	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.3	01	03	Nails	AMBCHFEFI	200A00200A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.3	01	08	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
2.3	01	02	Under Body	051Z04300H (Out of stock)	051Z04300HA	<b>NY</b>	<b>Old robots needs new item in Tab3-10 and Tab3-11</b>
2.3	01	01	Cap Set	Check on the spare part the new item code			
2.3	02	28	Safety Protection	051Z16200A & 051Z16100A	051Z28200A	YY	2016 Robot
2.3	02	06	Mother board		AM2010-30LP	NN	New model (6030EP0)
2.3	02	38	Keyboard extension		051Z27000A	YY	New item added.
2.3	03	10	Blade motor gasket	C01390	051Z21900B	<b>NN</b>	<b>Old body 051Z04300H use the old item</b>
2.3	03	11	Gasket plate	051Z05100A	051Z24600B	<b>NN</b>	<b>Old body 051Z04300H use the old item</b>
2.3	03	17	Battery Cabling		CB07_L30	YY	2016 Robot
2.3	03	31	Fixing plate	051Z00700A	051Z00700A2	YY	Replaced code
2.3	03	35	Heat gasket		051Z28400A	YN	2016 Robot
2.3	03	36	Heat gasket		051Z28300A	YN	2016 Robot
2.3	04	9	Bar		051Z26800A	YY	2016 Robot
<b>2015 Robots</b>							
2.2	04	08	Cover		051Z03800B black	YY	New item added. Check the color.
2.1	01	01	Screwdriver	110Z23900A	051Z20600A	NY	Old code was wrong
2.1	02	22a	Blade		075Z07800A	YY	New item added.
2.1	03	32	Gasket		051Z20000A	NN	New item added.
2.1	03	33	Gasket		051Z20100A	NN	New item added.
2.1	03	34	Washer		C00070	NN	New item added.
2.1	03	35	Screw		C01333	NN	New item added.
2.1	03	36	Cup		C01583	NN	New item added.

<b>Catalog.</b>	<b>TAB.</b>	<b>RIF.</b>	<b>Description</b>	<b>Old-Item</b>	<b>New-Item</b>	<b>Exchang.</b>	<b>Note</b>
2.0	02	14	Recharge Cabling	CB02_L30 ( on 2014 Robot )	CB02_PCL30	NN	
2.0	03	10	Gasket	C01151 ( on 2014 Robot )	C01390	YY	
2.0	03	26	Elastic plate	075Z08700A ( on 2014 Robot )	051Z05400B	YY	
2.0	04	01	Battery Charger	50_E0009_00 ( on 2014 Robot )	HLN60H29ZU	YY	
2.0	04	04	Transmitter	050Z22700A ( on 2014 Robot )	051Z17100A	NY	Please check the technical training note, to understand how to fix it, how to fix the wire connection and which features are available.
2.0	04	06	Recharging supply cable	CB01_30RIC_V0 ( 2014 Robot )	CB01_30S2	NN	



# Spare Parts Catalogue

MD-CO-RO-41

MODELS TYPE : (045BA0- 5045BA0

5045DE0- 5045EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

<b>YY</b>	Old and new components can be installed on new and old robots (interchangeability in both directions)
<b>NY</b>	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
<b>NN</b>	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
1.1	01	07	Pendulum	045A0045A	045A0045B	YY	
1.1	01	07	Pendulum	045A0050A	045A0050B	YY	
1.1	01	07	Pendulum	045A0055A	045A0055B	YY	
1.1	01	17	Kit Kanebo		045Z25400B	YY	Item added (24 teeth) instead of 48
1.1	04	09	Internal recharge	045Z19200C	045Z19200D	YY	
1.0	01	04	Power prong		CB02_PRNEM	NN	New item only for V3-V4 robots
1.0	04	16	Battery Wire	50_E0004_00	CB03_NEMO	YY	
0.5	01	01	Fix recharge kit	045Z24000A	045A0040A	YY	

