

Spare Parts Catalogue

MD-CO-RO-21
MODELS TYPE :
(7060BA0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2017 Robots							
4.0	01	05	Battery Charger	HLN60H29ZU	OWA60E30	YY	
4.0	02	03	Bumper		050Z31800A 050A00010A	NN	Grey Bumper Black Bumper
4.0	02	04	Spring		050Z31200A	NN	
4.0	02	05	Support		050Z31300A	NN	
4.0	02	06	Cap Set			NY	Check correct code on the catalog according to the brand.
4.0	02	07	Hall effect sensor		050E00900A	NN	
4.0	03	09	Screw	C00210	C00580	NN	
4.0	03	11	Gasket		50_D0049_00	YY	
4.0	03	12	Spacer		050Z31700A	NN	
4.0	03	14	Plate	050Z06600A	50_D0003_00	YY	
4.0	03	07	Gasket		50_D0050_00	YY	
4.0	04	10	Motherboard	50_SMEU_01	050E00700A	NN	



Spare Parts Catalogue

MD-CO-RO-22

MODELS TYPE : (7085EV0, 7085EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2017 Robots (7085EV0, 7085EL0)							
2.6	03	21	Mother board	AM2000-10B-SP	AM2000-12B-SP	YY	
2.5	02	01	Cap Set	085Axxxxxx	085Axxxxxx	NN	
2.5	02	08	Rech.Cabling	CB01_L7	CB07_L75	NN	
2.5	02	13	Free Wheel	075Z14600A	075Z31200A	NN	
2.5	02	29	Body	085Z16500A	075Z31800A 075Z32300A	NN	
2.5	03	13	Coil	CS_C0004_L	110E00700A 110A00100A	NN	Due to signal type TX-C1
2.5	03	22	Receiver	50_E0055_00	050E00500A	NN	Due to signal type TX-C1
2.5	04	02	Complete Base	075Z06200A_15N	075Z31600A	NN	Due to new transmitter
2.5	04	04	Transmitter	051Z17100A	051Z32500A	NN	Signal type TX-C1
2016 Robots – (5085DE0, 5085EV0, 5085EV1, 5085EL0)							
2.4	03	21	Mother Board	AM10-085xx	AM11-085xx	YY	Replace Code
2.4	04	01	(2A) Battery Charger	HLN60H29ZU	OWA60E30	YY	Replace item & Code
2.3	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.

2.3	01	03	Nails	AMBCHFEFI	200A00200A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.3	01	09	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
2.3	02	10 11 12	Wheel fixing system	C01209 C00360 C00361	C01767 C00361 C01766	YY	New wheels fixing system
2.3	02	20	Bell	075Z07600A.1	075Z07600AB	YY	
2.3	04	02	Complete Base	075Z06200A_V15	075Z06200A_15N	YY	
2.3	04	07	Plate support	075Z06300A.1	075Z06300A.3	YY	
2.3	04	08	Clips	C01101	C01559	YY	
2015 Robots							
2.2	02	27	Washer	C00217	C01265	NY	Old code was wrong
2.1	02	26	Screw	C00920	C01518	YY	
2.1	03	21	Motherboard	AM2010-75?	AM10-085?	YY	Full compatibility with 2014 robot
2.1	04	01	Battery Charger	50_E0009_00	HLN60H29ZU	YY	
2.1	04	02	Complete base	075Z06200A	075Z06200A_V15	YY	New base with a new transmitter.
2.1	04	04	Transmitter	050Z22700A	051Z17100A	NY	Please check the technical training note, to understand how to fix it, how to fix the wire connection and which features are available.
2.1	04	06	Recharging supply cable	CB01_5075RIC_V0	CB01_85S2	NN	



Spare Parts Catalogue

MD-CO-RO-23

**MODELS TYPE :
(7300EL0)**

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components cannot be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog g.	TA B.	RI F.	Description	Old-Code	New-Code	Exc.	Note
2017 Robots (7300EL0)							
5.8	04	04	Elastic plate	051Z05400B	110Z29200A	YY	Elastic plate with gasket
5.7	01		Reference 41 – Washer – on the previous spare part catalogue				No longer available
5.7	04	20	Bump board	CS_E0031_A	CS_E0031_C	NY	Replace code to support the backward compatibility
5.7	04	20	Bump board	CS_E0031_B	CS_E0031_D	NY	Replace code to support the backward compatibility
5.6	02	18	Lift board		300A00400A	NN	
5.6	02	04	Bolt		300Z01000A	NY	
5.6	02	20	Shaft Guide		051Z31000A	NN	
5.6	02	21	Bellows		110Z43500A	NN	
5.6	02	25	Shaft	300Z05400A 300Z05600A	300Z29900A 300Z30300A	NN	With magnet on the shaft
5.6	02	26	Front wheel	300A00001	110Z34200A	NN	Without magnet
5.6	02	27	Wheel Group	300A00020 300A00025	300Z29800A 300Z28900A	NN	
5.6	02	41	Washer		C02049	NN	
5.6	02	42	Washer		C00616	NN	
5.6	03	21	Underbody	300Z21300C	300Z30000A	NN	
5.6	04	17	Coil	CS_C0004_L	300A00300A	NN	
5.6	04	21	Display	200E01000A	300E01200A	NY	With connector for new lift system
5.6	04	31	Receiver	50_E0055_00	050E00500A	NN	Receiver for TX-C1
5.6	04	32	Bluetooth Receiver	051E00400A	051E01000A	YY	

5.6	04	36	Motherboard	AM11-300RL	AM2000-12B-SP	NY	Motherboard without software. "To be programmed"
5.6	04	40	Oring		C02103	YY	
5.6	04	28	Cube Board	300E00800A		NN	Item added
5.6	05	04	Complete Base	030Z12500AE	030Z12500AE_17	NN	Due to new transmitter
5.6	05	08	Transmitter	051Z17100A	051Z32500A	NN	Signal type TX-C1
2016 Robots (5300EL0)							
5.5	04	30	Cabling CPU-Display	CB01_D16_V1	CB01_DI6	YY	Replace Code
5.5	04	36	Mother Board	AM10-300RL	AM11-300RL	YY	Replace Code
5.5	05		Reference 13 – Roof – on the previous spare part catalogue				No longer available
5.5	05	15	Arch		030Z13000A	NY	New item added
5.4	02	32	Screw	C00781	C01246	NY	New item added
5.4	02	39	Washer		C01759	YY	New item added
5.4	02	40	Washer		C01247	YY	New item added
5.4	03	22	Segeer		C01936	YY	New item added.
5.4	03	11	Keyboard	300Z07900A	300Z18500A	YY	New code should be used on the cover with Stop button
5.4	04	39	Cabling		CB14_ADTPS	YY	New item added to manage old motherboard with new battery connector.
5.3	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	Docking base without countersunk holes : use old item code
5.3	01	03	Nails	AMBCHFEFI	200A00200A	YY	Docking base without countersunk holes : use old item code
5.3	01	10	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
5.3	02	3	Gasket	025_D0080	025_D0080.4	YY	Material & Price review
5.3	02	8	Cap set	300Z17500A.R	300Z17500ABR	YY	Material & Price review
5.3	03	5	Support	025_D0048_01	025_D0048_01B	YY	Material
5.3	03	20	Upper body	300_A0040_02	300_A0040_02	YY	Material & Price review
5.3	03	21	Under body	300Z21300C	300Z21300C	YY	Material & Price review
5.3	05	4	Charging base	030Z12500A_15	030Z12500AE	YY	Material & Price review
2015 Robots							
5.2	02	18	Rubber	300Z21600B 110Z05000A			No longer available.
5.1	03	7	Molla - Spring	025_D0082	300Z23400A	NY	
5.1	04	16	Gasket	300_C0009_00	300C000901	NY	



Spare Parts Catalogue

MD-CO-RO-25
MODELS TYPE :
(7200DE0, 7200EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2017 Robots							
5.7	04	15	Mother board	AM2000-10B-SP	AM2000-12B-SP	YY	
5.5	03	11	Bearing	C00119	200Z28000A 200Z28100A	YY	
5.4	02	19	Gasket	CS_D0070	CS_D0070/10	YY	
5.4	03	11	Bearing	CS_C0016A	C00119	NY	2017 production use C00119. CS_C0016A can be used only in 2016 production
5.3	03	35	Body Set	200Z23500A	200Z23500AB	NN	For old robot use item code 200A00018 instead of 200Z23500A. Price is 125€+tax
5.3	03	09	Lift Board	200Z04900A	200Z25900A	NN	
5.3	03	16	Front wheel	300A00001	110Z34200A	NN	Without magnet
5.3	03	17	Shaft	300Z01400A 300Z02900A	200Z26300A 200Z26500A	NN	With magnet on the shaft
5.3	03	21	Wheel Group	200A00010 200A00015	200Z26700A 200Z26600A	NN	
5.3	04	07	Coil	CS_C0004_L	110A00100A	NN	
5.3	04	10	Receiver	50_E0055_00	050E00500A	NN	Receiver for TX-C1
5.3	04	11	Bluetooth	051E00400A	051E01000A	YY	
5.3	04	15	Motherboard		AM2000-10A-SP AM2000-10B-SP	NY	Motherboard without software. "To be programmed"

5.3	04	16	Display	200E01000A		300E01200A		NY	With connector for lift system on the shaft
5.3	05	02	Complete Base	Please check on the catalog		BA210B_??17		NN	Due to new transmitter
5.3	05	08	Transmitter	051Z17100A		051Z32500A		NN	Signal type TX-C1
2016 Robots									
5.2	01	03	Nails	AMBCHFEFI_1		200A00100A		YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
5.2	01	03	Nails	AMBCHFEFI		200A00200A		YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
5.2	01	10	Wire connector			200A00003 200A00001 200A00050		YY	New item added.
5.2	05	2	Charging base		Check code			YY	Material & Price review
2015 Robots									
5.1	03	44	Screw	C00603		C00041		NY	Old code was wrong



Spare Parts Catalogue

MD-CO-RO-32

MODELS TYPE :
(7030BA0 - 7030DE0 - 7030ELO - 7030EP0- 7030ES0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	Old and new components can be installed on new and old robots (interchangeability in both directions)
NY	The new components can be installed both on new and old robots whereas old components can not be installed on new robots.
NN	The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2017 Robots (7030BA0 - 7030DE0 - 7030ELO - 7030EP0- 7030ES0)							
2.7	02	06	Mother board	AM2000-10B-SP	AM2000-12B-SP	YY	
2.7	03	38	Body	051A22000A	051A23500A	YY	New material
2.7	03	38	Body	051A21500A	051A23000A	YY	New material Only for 2016 Robots
2.6	01	07	Cabling	CB01RICINV3	CB01_RICEX	NN	
2.6	02	01	Cap Set	051R15xxxxx	051A17xxxxx	NN	2017 Cap Set
2.6	02	06	Mother Board	AM2011-30xx	AM2000-10A-SP AM2000-10B-SP	NY	Motherboard without software. "To be programmed"
2.6	02	11	Bluetooth rec.	051E00400A	051E01000A	YY	
2.6	02	29	Support		051Z27100A	YY	
2.6	02	12	Display	051Z13300A	051Z32400A	NY	
2.6	03	13	Coil	CS_L0004_L	051E01100A	YY	Coil with cabling
2.6	03	21	Shaft	075Z03600A	051Z34300A	NN	
2.6	03	26	Elastic plate	051Z05400B	110Z29100A	YY	
2.6	03	28	Washer		C02049	NN	
2.6	03	29	Washer		C00616	NN	
2.6	03	38	Body	051A21500A	051A22000A	NN	For 2016 Robot use the old code 051A21500A
2.6	03	41	Connector		CB08_L30	NN	
2.6	03	42	Lift board		051E26100A	NN	

2.6	03	43	Shaft Guide		051Z31000A	NN	
2.6	03	44	Bellows		110Z43500A	NN	
2016 Robots (5030BA0 - 5030DE0 - 5030EL0 - 6030EP0)							
2.5	02	06	Mother Board	AM2010-30xx	AM2011-30xx	YY	Replace Code
2.5	02	40	Spring		C01185	YY	New item added
2.5	02	41	Screw		C00087	YY	New item added
2.5	03	40	Gasket		051Z29100A	YY	New item added.
2.5	04	01	(2A) Battery Charger	HLN60H29ZU	OWA60E30	YY	Replace item & Code
2.5	04	01	(5A) Battery Charger		CS_CLG150-30	YY	New item added. Use only on the new model with 3 batteries "6030EP0"
2.4	02	39	Wheel cup		CS_D0183_04	YY	New item added.
2.4	03	12	Screw	C00210	C00208	NN	Use on 2016 Robot. Old robot needs C00210
2.4	03	16	Cabling Motherboard to battery		CB03_HR30	NN	Viewing in figure at TAB 3, use Ref. 16 : CB03_HR03 or Ref. 16a : CB03_L30
2.4	03	25	Washer		C01925	YY	New item added.
2.4	03	37	Under body	051Z04300HA	051Z04300HA	YY	Move from TAB 2.RIF 29
2.4	03	38	Under body		051A21500A	YY	New item added.
2.4	03	39	Seger		C01936	YY	New item added.
2.3	01	03	Nails	AMBCHFEFI_1	200A00100A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.3	01	03	Nails	AMBCHFEFI	200A00200A	YY	In docking station without countersunk holes, use the old code or adapt the hole to the new nail.
2.3	01	08	Wire connector		200A00003 200A00001 200A00050	YY	New item added.
2.3	01	02	Under Body	051Z04300H (Out of stock)	051Z04300HA	NY	Old robots needs new item in Tab3-10 and Tab3-11
2.3	01	01	Cap Set	Check on the spare part the new item code			
2.3	02	28	Safety Protection	051Z16200A & 051Z16100A	051Z28200A	YY	2016 Robot
2.3	02	06	Mother board		AM2010-30LP	NN	New model (6030EP0)
2.3	02	38	Keyboard extension		051Z27000A	YY	New item added.
2.3	03	10	Blade motor gasket	C01390	051Z21900B	NN	Old body 051Z04300H use the old item
2.3	03	11	Gasket plate	051Z05100A	051Z24600B	NN	Old body 051Z04300H use the old item
2.3	03	17	Battery Cabling		CB07_L30	YY	2016 Robot
2.3	03	31	Fixing plate	051Z00700A	051Z00700A2	YY	Replaced code
2.3	03	35	Heat gasket		051Z28400A	YN	2016 Robot

2.3	03	36	Heat gasket		051Z28300A	YN	2016 Robot
2.3	04	9	Bar		051Z26800A	YY	2016 Robot
2015 Robots							
2.2	04	08	Cover		051Z03800B black	YY	New item added. Check the color.
2.1	01	01	Screwdriver	110Z23900A	051Z20600A	NY	Old code was wrong
2.1	02	22a	Blade		075Z07800A	YY	New item added.
2.1	03	32	Gasket		051Z20000A	NN	New item added.
2.1	03	33	Gasket		051Z20100A	NN	New item added.
2.1	03	34	Washer		C00070	NN	New item added.
2.1	03	35	Screw		C01333	NN	New item added.
2.1	03	36	Cup		C01583	NN	New item added.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2.0	02	14	Recharge Cabling	CB02_L30 (on 2014 Robot)	CB02_PCL30	NN	
2.0	03	10	Gasket	C01151 (on 2014 Robot)	C01390	YY	
2.0	03	26	Elastic plate	075Z08700A (on 2014 Robot)	051Z05400B	YY	
2.0	04	01	Battery Charger	50_E0009_00 (on 2014 Robot)	HLN60H29ZU	YY	
2.0	04	04	Transmitter	050Z22700A (on 2014 Robot)	051Z17100A	NY	Please check the technical training note, to understand how to fix it, how to fix the wire connection and which features are available.
2.0	04	06	Recharging supply cable	CB01_30RIC_V0 (2014 Robot)	CB01_30S2	NN	



Spare Parts Catalogue

MD-CO-RO-33
MODELS TYPE :
(7250DE0, 7250EL0)

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

YY	<i>Old and new components can be installed on new and old robots (interchangeability in both directions)</i>
NY	<i>The new components can be installed both on new and old robots whereas old components can not be installed on new robots.</i>
NN	<i>The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability).</i>

Zucchetti Centro Sistemi Spa.

Catalog.	TAB.	RIF.	Description	Old-Item	New-Item	Exchang.	Note
2017 Robots (7250DE0, 7250EL0)							
1.2	04	04	Elastic plate	110Z29100A	110Z29200A	YY	Elastic plate
1.1	02	10	Disc	110Z33600C	110Z47900A	YY	Old one was wrong

